

Inventory

Sparkman & Stephens 37

Specifications

Reference/Stock No	Suraya
Make	Sparkman & Stephens
Model	37
Hull Material	Huon Pine, Mahogany Pilot house.
Length	37
Price	\$60,000
Region	RMYC Langkawi
Vessel Name	Suraya
Launch Year	1967
Beam	3.03m
Draft	1.60m
Displacement	8 Tonne
Deck material	Teak.
Keel/balast	Lead with moderate fin and separate Rudder
Designer	Sparkman & Stephens
Builder	McVilley of Hobart (TAS)
Registration Number	851537
Engine / Machinery	
Engine Make	Volvo
Engine Description	Replacement Volvo D130 30 hsp diesel engine.
Horsepower	30
Fuel Capacity	80L
Fuel Type	Diesel
Propulsion	Feathering folding prop (Hydraline).
Deck Hardware / Fittings	
Tender	Inflatable 2.7m with 3hsp outboard engine.
Ground Tackle /Anchor Winch	2 x anchors with Chain and Warp to suit.
Covers	Spray dodger, Sail cover. Full boat cover in fair condition.
Accommodation	
Accommodation Description	1 x quarter berth, 1 x convertible dinette in the saloon, 2 x pipe cots, and V-berth forward.

		1 x quarter berth, 1 x convertible dinette in the saloon, 2 x pipe cots, and V-berth forward.
Galley	Galley Description	2 x burner Kerosene Stove and oven. S/S sink with foot-operated tap.
	Refrigeration	12v portable fridge freezer and Icebox.
	Water Capacity	160L
Safety Equipment	Safety Gear	To be audited at time of survey. Near new 4 x man liferaft. 3 x pfd life jackets.
	Bilge Pumps	Manual & Electric.
Electrics / Electronics	Electrics	12v
	Instruments / Navigation	Interactive AIS, B&G triton, new chart plotter 7â€ and charts for S/E Asia. New head unit for wind instruments NOT fitted. Sinrad Auto pilot x 2.
Sail / Rigging	Sail Inventory	Dacron Main sail (by Hood sails), cruising Jib on Furler, Racing sails #1, #2, and #3. 2 x Spinnakers (1 x light and 1x heavy), storm Jib and Tri-Radial Main sail.
	Mast / Rigging	Single spreader Aluminium Rig (by Jo Walsh Rigging). Aluminium Boom, all rope Halyards, Pro-furl Jib Furler with new Forestay and Aluminium Spinnaker pole.
	Deck Gear	7 x winches.
Miscellaneous	General Remarks	2 x 12v battery banks (4 x batteries in total), 2 x batteries recently replaced